PRODUCT-DETAILS

MTE354300WFACA0001

M3BP355LKB8G - Pn: 400 cv, 300 kW - 8P - Frame 355 - M3BP 355LK - Mounting B35

General Information

Global Commercial Alias	MTE354300WFACA0001
Product ID	MTE354300WFACA0001
ABB Type Designation	M3BP355LKB8G
Catalog Description	M3BP355LKB8G - Pn: 400 cv, 300 kW - 8P - Frame 355 - M3BP 355LK - Mounting B35

Ordering

ABB Type Designation	M3BP355LKB8G
Invoice Description	M3BP355LKB8G - Pn: 400 cv, 300 kW - 8P - Frame 355 - M3BP 355LK - Mounting B35
Product Name	Low Voltage Motor
Product Type	3BP3__M3BP_IE3_CI
Made To Order	No
Minimum Order Quantity	1 piece
Order Multiple	1 piece
Selling Unit of Measure	piece
Country of Origin	Switzerland (CH)
Customs Tariff Number	85015310
Stocked At (Warehouses)	Bairro Santo Antonio, Brazil

Electrical

Electrical Data

2024/10/26 Subject to change without notice

ABB

2024/10/26

2024/10/26

Subject to change without notice

2024/10/26

Conn

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

Altitude	1000 m
Ambient Temperature	40 °C
IC Class	IC411
IE Class Data (60 Hz)	IE Class IE3 Full Load (100%) 80.5 % Partial Load (75%) 79.5 % Partial Load (50%) 76.2 %
IP Class	IP55
Insulation Class	ICLF
Direction of Rotation	Both sides
Number of Poles (High)	8
Two Speed Motor	No
Type of Duty	S1
Voltage Code	S

Mechanical

Frame Material	Cast Iron
Frame Size	355
Bearing	6322/C3
Bearing NDE	6316/C3
IM Class	IMV3 IM3031
Terminator Box Location	D-End top

Dimensions

Product Net Depth / Length	1000 mm
Product Net Height	1000 mm
Product Net Width	1000 mm
Product Net Weight	2600 kg
Gross Weight	0 kg

2024/10/26   Subject to change without notice

Temp Class

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

2024/10/26   Subject to change without notice

Freq

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

Voltage

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

2024/10/26 Subject to change without notice

Power

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

2024/10/26 Subject to change without notice

Speed

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

2024/10/26 Subject to change without notice

Current

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

Power Factor

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

2024/10/26

Subject to change without notice

Efficiency

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox ":
The expression contains undefined function call GetListItemValue().

Torque

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

2024/10/26
Subject to change without notice

IS/IN

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

An error has occurred while processing HtmlTextBox '':
The expression contains undefined function call GetListItemValue().

Categories

Motors and Generators → IEC Low Voltage AC Motors → Process Performance Motors → IR3 Premium Efficiency Motors